

SIMON LEAD WATER TEST RESULTS

May 24th, 2016



Building Location	Sample Collected	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2n Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 SIMON ELEMENTARY SCHOOL	Date 5/11/2016	WS- 010217	Classroom	1	In parents resource room	WT-042916-10234- A	< 1	WT-042916-10234- B	< 1				+
2 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010293	Cooler	1	In hallway adjacent to 105	WT-042916-10310- A	< 1	WT-042916-10310- B	< 1				
3 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010294	Cooler	1	In hallway adjacent to 116	WT-042916-10311- A	< 1	WT-042916-10311- B	< 1				
4 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010295	Fountain	1	In classroom 115	WT-042916-10312- A	< 1	WT-042916-10312- B	< 1				
5 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010296	Fountain	1	In classroom 115	WT-042916-10313- A	< 1	WT-042916-10313- B	< 1				
6 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010297	Classroom	1	In classroom 114	WT-042916-10314- A	< 1	WT-042916-10314- B	< 1				
7 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010298	Fountain	1	In classroom 114	WT-042916-10315- A	< 1	WT-042916-10315- B	< 1				
8 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010299	Cooler	2	In hallway adjacent to 211	WT-042916-10316- A	< 1	WT-042916-10316- B	< 1				
9 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010300	Cooler	2	In hallway adjacent to 205	WT-042916-10317- A	< 1	WT-042916-10317- B	< 1				
10 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010301	Classroom	2	In classroom 202 Right	WT-042916-10318- A	5.6	WT-042916-10318- B	1.2				
11 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010302	Cooler	3	In hallway adjacent to 305	WT-042916-10319- A	< 1	WT-042916-10319- B	< 1				
12 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010303	Cooler	3	In hallway adjacent to 309	WT-042916-10320- A	< 1	WT-042916-10320- B	< 1				
13 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010304	Cooler	Ground Floor	In hallway adjacent to 013	WT-042916-10321- A	< 1	WT-042916-10321- B	< 1				
14 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010305	Classroom	Ground Floor	In classroom 014	WT-042916-10322- A	1.7	WT-042916-10322- B	1.1				
15 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010306	Fountain	Ground Floor	In classroom 014	WT-042916-10323- A	2.2	WT-042916-10323- B	< 1				
16 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010307	Fountain	Ground Floor	In classroom 015	WT-042916-10324- A	1.6	WT-042916-10324- B	< 1				
17 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010308	Classroom	Ground Floor	In classroom 015	WT-042916-10325- A	< 1	WT-042916-10325- B	< 1				
18 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010309	Health Suite	Ground Floor	In health suite 013	WT-042916-10326- A	< 1	WT-042916-10326- B	< 1				
19 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010310	Classroom	Ground Floor	in room 1012	WT-042916-10327- A	< 1	WT-042916-10327- B	< 1				
20 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010311	Kitchen	Ground Floor	In kitchen	WT-042916-10328- A	< 1	WT-042916-10328- B	3				
21 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010312	Utility	Basement	In boiler room (water source)	WT-042916-10329- A	27.5	WT-042916-10329- B	13.6	Non-drinking water source - Not accessible to children			
22 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010313	Cooler	Basement	In hallway adjacent to classroom 003	WT-042916-10330- A	< 1	WT-042916-10330- B	1				
23 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010314	Classroom	Ground Floor	In teachers launch	WT-042916-10331- A	< 1	WT-042916-10331- B	< 1				
24 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010315	Classroom	2	In classroom 202 Left	WT-042916-10332- A	3.2	WT-042916-10332- B	2				
25 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010316	Fountain	Ground Floor	In classroom 001	WT-042916-10333- A	3.3	WT-042916-10333- B	< 1				
26 SIMON ELEMENTARY SCHOOL	5/11/2016	WS- 010317	Classroom	Ground Floor	In classroom 001	WT-042916-10334- A	1.3	WT-042916-10334- B	< 1				

- Footnotes:

 A First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B Second draw sample is collected after a 60 second flush at that device after the first draw.